

CF 3000 LOC 1,0 - Spare locator

1205655

<https://www.phoenixcontact.com/us/products/1205655>



Please be informed that the data shown in this PDF document is generated from our online catalog. Please find the complete data in the user documentation. Our general terms of use for downloads are valid.



Sleeve receiver for 1.0 mm² sleeves

Product description

Replacement locator, 1.0 mm²

Commercial data

Item number	1205655
Packing unit	1 pc
Minimum order quantity	1 pc
Sales key	BH32
Product key	BH323Y
GTIN	4017918137601
Weight per piece (including packing)	4.5 g
Weight per piece (excluding packing)	4.5 g
Customs tariff number	84799070
Country of origin	DE

CF 3000 LOC 1,0 - Spare locator

1205655

<https://www.phoenixcontact.com/us/products/1205655>



Technical data

Product properties

Product type	Sleeve receiver
--------------	-----------------

Connection data

Conductor cross-section flexible	1 mm ² ... 1 mm ²
----------------------------------	---

CF 3000 LOC 1,0 - Spare locator

1205655

<https://www.phoenixcontact.com/us/products/1205655>



Approvals

🔗 To download certificates, visit the product detail page: <https://www.phoenixcontact.com/us/products/1205655>



EAC

Approval ID: RU C-DE.AI30.B.01549

CF 3000 LOC 1,0 - Spare locator

1205655

<https://www.phoenixcontact.com/us/products/1205655>



Classifications

ECLASS

ECLASS-13.0	17130191
ECLASS-15.0	17130191

ETIM

ETIM 10.0	EC000163
-----------	----------

UNSPSC

UNSPSC 21.0	27111500
-------------	----------

CF 3000 LOC 1,0 - Spare locator



1205655

<https://www.phoenixcontact.com/us/products/1205655>

Environmental product compliance

EU RoHS	
Fulfills EU RoHS substance requirements	Yes, No exemptions
EU REACH SVHC	
REACH candidate substance (CAS No.)	No substance above 0.1 wt%
EF3.1 Climate Change	
CO2e kg	0.835 kg CO2e

Phoenix Contact 2026 © - all rights reserved
<https://www.phoenixcontact.com>

Phoenix Contact USA
586 Fulling Mill Road
Middletown, PA 17057, United States
(+717) 944-1300
info@phoenixcon.com